

JOSEPH[®]
JOSEPH

SwitchScale™

2-in-1 digital scale with
reversible lid



ENGLISH

FULL DISPLAY



SPECIFICATION

- Equipped with 4 high-precision sensors.
- Weight units: g / lb oz / ml / fl.oz
- Capacity: 5 kg / 11lb / 5000 ml / 176.4 fl.oz
- Graduation: 1 g / 1 lb / 1 ml / 0.1 fl.oz
- Weight range: 1 g - 5 kg (5000 g)
- Power supply: 3 x AAA battery (included).
- Low battery indication: 'Lo'.
- Overload indication: 'EEEE'.
- Auto shut-off: Turns off after 5 minutes of non-use.

TO INSERT/CHANGE BATTERY

1. Locate the battery compartment on the underside of the scale.
2. Ensure battery is inserted the correct way around.

TO SWITCH ON

Press the ZERO /  key.

TO SWITCH OFF

Press and hold the ZERO /  key for two seconds.

SELECT WEIGHT UNIT

When the scale is on, press the UNIT key to select the units.

OPERATION INSTRUCTIONS

Place scale on a flat surface prior to use.

Please note: Touch-sensitive buttons – press gently.

To weigh:

1. Press the ZERO /  key. All display figures will appear before setting to zero.
2. Press the UNIT key to select the units required.
3. Place item to be weighed carefully onto scale.
4. To turn off the scale, press and hold the ZERO /  key.

Add & Weigh function:

Press the ZERO /  key, after 1 second the LCD will display 0g (see Figure 1).



Figure 1



Figure 2

Overload:

SwitchScale™ can measure accurately up to 5250g. When the weight exceeds

5250g the LCD will show the overloading display (see Figure 2).

ADDITIONAL INFORMATION

- This scale is not waterproof. Do not expose to moisture.
- Before use, make sure your scale is at room temperature and on a stable, horizontal surface, free of vibration.
- Store your scale in a clean, dry location. Dust, dirt and moisture can accumulate on the weighing sensors and electronics causing inaccuracy or malfunction.
- Gently place all items to be weighed. Do not drop items onto the scale.